



1995 Citation VI

- Engines and APU on MSP Gold
- Professionally Flown and Maintained
- Excellent pedigree, two owners since new
- Recent inspections

Disclaimer: All specifications and descriptions herein are provided as preliminary information and do not constitute representations or warranties. Verification remains the sole responsibility of the purchaser. Interested parties are encouraged to conduct their own independent pre-purchase evaluation at a qualified facility. The Dyer Group, Inc. makes no representations as to the airworthiness of the aircraft. Aircraft subject to prior sale and removal from market.

AIRFRAME

Total Time:	8960 hours
Total Landings:	8622
Maintenance Tracking:	Veryon

ENGINES (HONEYWELL MSP GOLD)

	Engine #1	Engine #2
Make/Model:	TFE731-3CR-100S	TFE731-3CR-100S
Serial Number:	P-108129	R-108130
Total Hours:	8647	8735
Total Cycles:	8337	8258

APU (HONEYWELL MSP GOLD)

Total Time:	4189 hours
Model:	GTCP36-150(W)
Serial Number:	P-214

INTERIOR

Beautiful 8 passenger executive configuration consisting of a forward-cabin 2-place divan, 2 mid-cabin aft facing seats, aft-cabin 4-place club. All seats are tan leather. The cabin has light grey carpet and light tan sidewalls. The interior has a forward refreshment center and coat closet. Aft lavatory.

EXTERIOR

Overall Matterhorn white fuselage with black and gold striping.

AVIONICS

ADF: Collins ADF-60A

Navigation Radios: Dual Collins VIR-32A

Autopilot: Honeywell SPZ-650

Radar Altimeter: Collins ALT-55

Communication Radios: Dual Collins VHF-22A

RMI: Dual Collins RMI-36

CVR: Fairchild GA-100

SATCOM: Aircell ST-3100 Telephone Receiver

DME: Dual Collins DME-42

TCAS: Bendix King TPU-67A TCAS II

EFIS: Honeywell EDZ-600 5-Tube

Transponder: Dual Collins TDR-94
(W/ Skylight CMD DDA Adapter)

Flight Director: Honeywell SPZ-650 IFCS

Weather Radar: Honeywell Primus 650

FMS: Dual Universal UNS-1LW

MAINTENANCE INSPECTIONS

	LAST DONE	NEXT DUE
Document 1 (12 Month/400 hr)	July 2026/8943	July 2027/9360
Document 2 (400 hr)	June 2025/8960	9360
Document 3 (12 Month)	July 2026	July 2027
Document 4 (24 Month)	June 2025	June 2027
Document 5 (24 Month)	July 2026	July 2028
Document 6 (800 hr)	8227	9027
Document 7 (24 Month)	July 2026	July 2028
Document 8 (36 Month/1200 hr)	July 2026/10049	July 2029/11249
Document 9 (36 Month)	July 2025	July 2028
Document 11 (72 Month)	October 2025	October 2031
Document 19 (72 Month/2400 hr)	July 2026	July 2032
Document 28 (6 Month)	July 2026	November 2026
Document 42 (12 Month)	July 2026	July 2027
Document 48 (24 Month)	July 2026	July 2028
Document 50 (6 Month)	July 2026	January 2027

Exterior view



Cockpit



Forward side-facing divan



Forward refreshment center



Forward refreshment center



Forward cabin, facing aft



Mid cabin, detail



Aft cabin, detail



Aft lavatory



Aft cabin club section, facing forward



Mid cabin, facing forward



Forward divan, facing forward



Cabin detail



Exterior



Exterior





CONTACT US

Andy Dyer
President

Office (864) 232-0551
Mobile (864) 616-4020
Email: andy@dyerjet.com

2502B Wade Hampton Blvd.
Greenville, SC 29615

Denis Jubinville

Managing Partner / West

Mobile (949) 784-9632
Email: denis@dyerjet.com

19711 Campus Drive, suite 220
Santa Ana, CA 92707

Stephen Wood
Senior Appraiser / Sales

Office (864) 232-0551
Mobile (864) 325-3376
Email: stephen@dyerjet.com

2502B Wade Hampton Blvd.
Greenville, SC 29615

Ashton Dyer
Market Research/Sales

Office (864) 232-0551
Mobile (864) 501-7700
Email: ashton@dyerjet.com

2502B Wade Hampton Blvd.
Greenville, SC 29615

Disclaimer: All specifications and descriptions herein are provided as preliminary information and do not constitute representations or warranties. Verification remains the sole responsibility of the purchaser. Interested parties are encouraged to conduct their own independent pre-purchase evaluation at a qualified facility. The Dyer Group, Inc. makes no representations as to the airworthiness of the aircraft. Aircraft subject to prior sale and removal from market.